

Schrader Components

Part #	Connection	Pkt
55-1	SCHRADER VALVE CORE	10
55-1-410A	SCHR VALVE CORE-410A	10
55-2	SCHRADER CAP-with O'Ring	10
55-2-410A	SCHR CAP & O'RING-410A	10
55-3	SCHRADER CAP with TOOL	10
55-4	"O" ring (Included with cap)	10
55-5	SCREW DEPRESSOR +3 gasket	10
55-2AL	ALUMINIUM CAP	10



Schrader Crosses 3 Schraders x 1 Male thread

Part #	Connection	Pkt
	Schrader x Male NPT	
53-04040402	1/4 SCHR x 3 x 1/8 MNPT	1
53-04040404	1/4 SCHR x 3 x 1/4 MNPT	1
	Schrader (Swivel) x Male NPT	
53-04040404S	1/4 SCHR x 2 x F/SWIVEL x 1/4 MNPT	1
	Schrader x Male BSP	
54-04040402	1/4 SCHR x 3 x 1/8 MBSP	1
54-04040404	1/4 SCHR x 3 x 1/4 MBSP	1
	Schrader (Swivel) x Male BSP	
54-04040404S	1/4 SCHR x 2 x F/SWIVEL x 1/4 MBSP	



Schrader Unions

Schrader x Male SAE Flare

Part #	Connection
55-0404	1/4 SCHR x 1/4 MSAE


Schrader x Male BSP

56-0402	1/4 SCHR x 1/8 MBSP
56-0404	1/4 SCHR x 1/4 MBSP
56-0504-410A	5/16 SCHR x 1/4 MBSP-410A
57-0402	1/4 SCHR x 1/8 MNPT
57-0404	1/4 SCHR x 1/4 MNPT



Schrader Flare to Copper Tail 60mm extensions

Part #	Connection	Pkt
58-0402	1/4 SCHR x 1/8 CU Tail	5
58-0403	1/4 SCHR x 3/16 CU Tail	5
58-0403-TC	1/4 SCHR x 3/16 CU Tail + Tool	
	Cap&Core	5
58-0404	1/4 SCHR x 1/4 CU Tail	5
58-0404/50	1/4 SCHR x 1/4 CU Tail	50
58-0404/100	1/4 SCHR x 1/4 CU Tail	100
58-0404A1	As Above - exclude Cap & Core	5
58-0404A1/50	As Above - exclude Cap & Core	50
58-0404-TC	1/4 SCHR x 1/4 CU Tail + Tool	
	Cap&Core	5
58-0404-TC/50	1/4 SCHR x 1/4 CU Tail + Tool	
	Cap&Core	50
58-0405	1/4 SCHR x 5/16 CU Tail	5
58-0406	1/4 SCHR x 3/8 CU Tail	5
58-0504-410A	5/16 SCHR x 1/4 CU Tail - 410A	5



Schrader Step Unions

Schrader Flare to Steps

Part #	Connection
59-0403-3	1/4 SCHR - 3 STEP 3/16 to 3/8
59-0403-3/50	1/4 SCHR - 3 STEP 3/16 to 3/9
59-0404	1/4 SCHR - 1/4 ID for TUBE
60-04-5	1/4 SCHR - 5 STEP 1/8to1/2



Schrader Elbows

Flare to Male Taper BSP

Part #	Connection
61-0402	1/4 SCHR x 1/8 MBSP
61-0404	1/4 SCHR x 1/4 MBSP

Schr Flare to Male Taper NPT

62-0402	1/4 SCHR x 1/8 MNPT
62-0404	1/4 SCHR x 1/4 MNPT

Schr Flare to Female SWIVEL SAE

63-0404	1/4 SCHR x 1/4 F/SWIVEL SAE
---------	-----------------------------



Schrader Swivel Tees

Swivel Nut on branch

Part #	Connection	Pkt
64-040404	1/4 SCHR x 1/4 SCHR x 1/4 FSAE	2
64-040404D	1/4 SCHR x 1/4 SCHR x 1/4 FSAE (with depressor and seal in nut)	2
64-050505D -410A	5/16 SCHR LINE x 5/16 FSAE-410A	2



Schrader Tees

Swivel Nut on the run

Connection	Pkt	Swivel Nut on the run Part #
65-040404	1/4 FSAE x 1/4 SCHR x 1/4 SCHR	2
65-040404D	1/4 FSAE x 1/4 SCHR x 1/4 SCHR	2



Schrader Step Tees


Tee with stepped run and schrader branch

Part #	Connection	Pkt
66-040404	SCHR x 1/4", 5/16" STEP x SCHR	2



Schrader on run lines to Female SAE Branch

Part #	Connection	Pkt
67-040404	1/4 SCHR x 1/4 SCHR x 1/4 FSAE	2



Schr Flare to MBSP

68-040404	1/4 SCHR x 1/4 SCHR x 1/4 MBSP	2
-----------	--------------------------------	---

Schr Flare to MNPT

Part #	Connection	Pkt
69-040402	1/4 SCHR x 1/4 SCHR x 1/8 MNPT	2
69-040404	1/4 SCHR x 1/4 SCHR x 1/4 MNPT	2



Schrader Union 410A

Part #	Connection	Pkt
274-0405D-410A	1/4 MSAE schr x 5/16 FSAE-410A	1
274-0504D-410A	5/16 MSAE schr x 1/4 FSAE-410A (with depressor and seal)	1
274-0506-410A	5/16 MSAE schr x 3/8 FSAE-410A	1

